

**NEW SUNRISE CO., LTD.**

TEL: +86 512 66733733

FAX: +86 512 66730261

Email: info@nsrmarine.com

www.nsrmarine.com



## NSR Technical Notice

NSR22-TN02

Issued on 18<sup>th</sup> April 2022

### 1. Problem description

NVR-3000's receiving voice in main speaker is still too loud even when adjusted to the lowest level by the volume control.

### 2. Products affected

Serial numbers: **VR210604--VR210800**

Firmware version: **V1.00, V1.01, V1.02**

Shipped date from NSR: **from June 2021 to December 2021.**

### 3. How to fix above bug?

The above bug has been fixed since firmware V1.03.

The latest firmware V1.05 can be downloaded in DISTRIBUTOR AREA at NSR website.

### 4. About firmware versions of NVR-3000

Version No.	Firmware Description	Main purposes
V1.00	App_NVR301_20210602_V100	Initial version
V1.01	App_NVR301_20210910_V101	Improve BAM function Add ATIS muting function Fix some known bugs
V1.02	App_NVR301_20211029_V102	Modify DSC function to receive DSC call with own MMSI
V1.03	App_NVR301_20211230_V103	Control the lowest voice volume in main speaker
V1.04	App_NVR301_20220224_V104	Fix some known bugs Improve Channel Watch Scan
V1.05	App_NVR301_20220302_V105	Fix some known bugs

Issued by NSR A/S, Q/A, R&D