

## NSR Technical Notice

NSR22-TN04

Issued on 1<sup>st</sup> July 2022

### 1. Problem description

Wrong name plate stickers were used on NTW-1000 or its batteries NBT200/NBT200C. On those stickers, notified body and year for wheelmark are missing. See below photo.



### 2. Products affected

Some of those NTW-1000 products shipped from NSR around May 2022.

### 3. Action to be taken

NSR will provide free replacement of affected products with new ones carrying correct name plate stickers for NSR distributors/dealers.